

**APPENDIX A**  
**SITE PHOTOGRAPHS**

**Marks Creek Mitigation Site Photo Points**



Photo Point #1. Facing south along the North Tributary - 2005



Photo Point #2. Facing east along West Tributary - 2005





Photo Point #3. Facing east along South Tributary - 2005



Photo Point #4. Facing west along South Tributary - 2005





Photo Point #4. Facing northeast along South Tributary - 2005



Photo Point #5. Facing north across South, West and North Tributaries - 2005





Photo Point #5. Facing northwest across South and West Tributaries - 2005



Photo Point #5. Facing southwest along South Tributary - 2005





Photo Point #6. Facing east along Main Channel – 2005



Photo Point #6. Facing north across confluence of Main Channel and North Tributary - 2005



Photo Point #6. Facing west at confluence of West and South Tributaries - 2005



## Individual Photographs – North Tributary

---



Undercut log vane at Station 13+63 along the North Tributary – 2005





Vegetation within the bankfull channel between Stations 12+34 and 16+15 along the North Tributary – 2005.



## Individual Photographs – West Tributary

---



Vegetation within the bankfull channel between Stations 11+07 and 12+70 along the West Tributary – 2005





Localized bank erosion at Station 13+00 along the West Tributary – 2005





Undercut cross vane at Station 13+18 along the West Tributary – 2005

Vegetation within the bankfull channel between Stations 13+35 and 15+55 along the West



Tributary - 2005



## Marks Creek Mitigation Site – South Tributary

---



Vegetation within the bankfull channel between Stations 15+00 and the end of the reach associated with the South Tributary – 2005



Vegetation within the bankfull channel at Station 16+00 along the South Tributary - 2005





Vegetation within the bankfull channel near Station 10+00 along the Southwest Tributary - 2005